

1842Z 19 FEB 68

S E C R E T

ceruno

cont
Fin

DIRECTOR


25X1A

OPD (1,2,3,4,5,6,7,8,9,10)


S/C (11)

RLU

TMR: 1842Z 19 FEB 68




25X1A



25X1A

ROUTINE

IN-18298



25X1A



LENGTHY BENCH CHECKS OF SYSTEM III REVEAL INTERMITTENT
OPERATION 3RD LO BOARDS. JIG TESTS INDICATE DIFFERENCES IN
BOARD CIRCUITRY, AND MODIFIED SYSTEM III SCHEMATICS. 2 MONTHS
3RD LO BOARD TURN-AROUND UNSATISFACTORY. REQUEST 30 DAY TECH
REP ASSISTANCE TO EXPEDITE SOLUTION THIS PROBLEM. UNDERSTAND
A QUALIFIED TECH REP IS PRESENTLY LOCATED

25X1A

END OF MESSAGE

84
801
701
141286 141286 0109855

S E C R E T